Monitoring Data Record

Project Title: R-2547C (Site 7) COE Action ID: 2002-2-0819 Extraor Name: UT to Marks Creek DWO Numbers: 011680
Stream Name: <u>UT to Marks Creek</u> DWQ Numbers: <u>011689</u>
City, County and other Location Information: Wake County, Knightdale Bypass
Sta. 131+00 to 133+00-L-)
Date Construction Completed: November 2004 Monitoring Quarter: (8) of 8
Ecoregion: 8 digit HUC unit: 03020201
USGS Quad Name and Coordinates:
Rosgen Classification:
Length of Project: 262' Urban or Rural: Rural Watershed Size:
Monitoring DATA collected by: J. Young Date: 2/19/08
Applicant Information:
Name: NCDOT Roadside Environmental Unit
Address: 1425 Rock Quarry Rd. Raleigh, NC 27610
Telephone Number: (919) 861-3772 Email address: mlgreen@dot.state.nc.us
Consultant Information:
Name:
Address:
Telephone Number: Email address:
Project Status: Complete
Troject Status. Complete
Monitoring Level 1 requires completion of Section 1, Section 2 and Section 3 Permit States: The permittee will visually monitor the vegetative plantings on all mitigation streambanks to access and insure complete stabilization of the mitigation stream segments. This monitoring will include adequate visual monitoring of planted vegetation for a minimum of two years after final planting, and appropriate remedial actions (e.g., replanting, streambank grading,
cect.). If within any monitoring year, bank stabilization is not acceptable as determined by the Corps of Engineers, and remedial action required by the Corps of Engineers is performed, the two year monitoring of the affected portions of the stream will begin again. Section 1. PHOTO REFERENCE SITES
ect.). If within any monitoring year, bank stabilization is not acceptable as determined by the Corps of Engineers, and remedial action required by the Corps of Engineers is performed, the two year monitoring of the affected portions of the stream will begin again.
Corps of Engineers, and remedial action required by the Corps of Engineers is performed, the two year monitoring of the affected portions of the stream will begin again. Section 1. PHOTO REFERENCE SITES Total number of reference photo locations at this site: B photo point locations - 2 photos at each location Dates reference photos have been taken at this site: 4/18/06, 8/4/06, 11/15/06, 3/14/07,
Corps of Engineers, and remedial action required by the Corps of Engineers is performed, the two year monitoring of the affected portions of the stream will begin again. Section 1. PHOTO REFERENCE SITES Total number of reference photo locations at this site: B photo point locations - 2 photos at each location Dates reference photos have been taken at this site: 4/18/06, 8/4/06, 11/15/06, 3/14/07,
ect.). If within any monitoring year, bank stabilization is not acceptable as determined by the Corps of Engineers, and remedial action required by the Corps of Engineers is performed, the two year monitoring of the affected portions of the stream will begin again. Section 1. PHOTO REFERENCE SITES Total number of reference photo locations at this site: 8 photo point locations - 2 photos at each location Dates reference photos have been taken at this site: 4/18/06, 8/4/06, 11/15/06, 3/14/07, 5/31/07, 8/9/07, 11/21/07, 2/19/08

Section 2. PLANT SURVIVAL

If required to complete Level 1 and Level 2 monitoring <u>only</u> stop here; otherwise, complete section 3.

Section 3. CHANNEL STABILITY

Visual Inspection: The entire stream project as well as each in-stream structure and bank stabilization/revetment structure must be evaluated and problems addressed.

Report on the visual inspection of channel stability. Physical measurements of channel

and an evaluation of the significance of these deviations and whether they are indicative of a
stabilizing or destabilizing situation.
The stream is stable for the 8th quarter of monitoring. NCDOT proposes to discontinue monitoring at this stream
relocation.

stability/morphology will not be required. Include a discussion of any deviations from as-built

Date	Station	Station	Station	Station	Station
Inspected	Number	Number	Number	Number	Number
Structure					
Type					
Is water					
piping					
through or					
around					
structure?					
Head cut or					
down cut					
present?					
Bank or scour					
erosion					
present?					
Other					
problems					
noted?					

NOTE: Attach separate narrative sheets to each monitoring report describing/discussing the overall monitoring results. Include the identification of specific problem areas/channel failures, estimated cause and proposed/required remedial action. This should include a brief discussion of any parameter that has changed significantly from as-built.

Site 7



Photo 1 (Upstream)



Photo 2 (Downstream)



Photo 3 (Upstream)



Photo 4 (Downstream)



Photo 5 (Upstream)



Photo 6 (Downstream)

8th Quarter – February 2008